

[Type here]

Taluk Health Office, Bagepalli Taluk,

Chikkaballapur District. Email : thobag2015@gmail.com, ph:08150-283310

APPENDIX – VIII

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No :

Date : 11-03-2025

It is certified that an inspection team headed by Dr . Sathyanarayana Reddy C N, Taluk Health Officer Bagepalli Taluk inspected **BLOOMS INTERNATIONAL SCHOOL**, located at Karkur Cross, Bagepalli Taluk, Chikkaballapur District – 5612507, run by **Sri Chaithanya Educational Trust** ® On 11-03-2025 and found that the **BLOOMS INTERNATIONAL SCHOOL**, has safe drinking water facilities for the students and members of staff of the Institution and maintaining the hygienic sanitation condition in the school building and the campus as per the norms prescribed by the Central/State/U.T Government.

The above is valid for a period of 2 years.

Sd/-

Dr. Sathyanarayana Reddy
DR. SATHYANARAYANA REDDY C.N.
TALUK HEALTH OFFICER
BAGEPALLI TALUK
CHIKKABALLAPUR DIST-561207.

To

BLOOMS INTERNATIONAL SCHOOL.

Karkur Cross

Bagepalli Taluk,

Chikkaballapur District - 561207

GOVERNMENT OF KARNATAKA

Office of the Joint Director
Public Health Institute
Bengaluru - 560 001

No:PHI/Water/BAC/

112/25-26

Report of Bacteriological analysis of Water/Effluent sample

Dated:

02-05-2025

Sample No.	Source & Particulars of Water Sample	Opinion				
		M.P.N Count	Plate Count	D.C Test	S.P.P	N.S.P.P & FC.
365	RO Sub-tem B-Xb-2129287	N/A	-	-	SPP	-
<p>Note:</p> <p>M.P.N Count: Most probable number of Bacteria per 100ml of Water</p> <p>D.C Test: Differential Coliform test</p> <p>Plate Count: Plate Count per ml of sample</p> <p>SPP: Water is satisfactory for Potable purpose</p> <p>NSPP: Water is not satisfactory for Drinking purpose</p> <p>NSPP & FC: Water is not satisfactory for Drinking purpose and E.Coli found</p>						

For Joint Director (Lab)

Public Health Institute

For Joint Director (Lab) Circle,

PUBLIC HEALTH INSTITUTE

Bengaluru

(PRO)